

COMMISSIONINGREQUEST FORM

Please be aware the boiler must be commissioned within 3 months of the installation date to qualify for the full warranty.

SITE DETAILS		
Site contact name	Site name	
Ric	Aston House	
Site contact number 1 07595603697	Site contact number 2 07595603697	
Site address	Site Postcode	
Aston House 19 barrow Lane Hale	Wa150dn	

	BOILER 1	
Boiler model Heat 2		
Output		

Full serial number
AFL22082100001797

Date code
17 08 23

Installation date
18-Sep-23

Purchase date
24-Aug-23

Merchant purchased from
Plumb centre

Branch
Bolton

Is a Keston 28mm System Filter fitted

Yes

INSTALLER DETAILS

Contact name

Richard Renzulli

Contact number

07595603697

Company name

Ace heating

Email address

ricrenzulli@hotmail.com

Company Gas Safe Registration

541950

Company address

219 Whittingham drive Ramsbottom

Company Postcode

Bl09ny

APPOINTMENT DETAILS

Requested visit date

02/10/2023

Is a Site Induction necessary?

No

Do our engineers require CSCS cards?

No

Are Risk Assessment / Method Statements required?

No

Please note the system must be cold and have sufficient heat load so all boilers can be fired full rate

REPORTS

Please provide at least 2 email addresses for the report and warranty certificate (where applicable) upon completion of a successful commissioning

Email address 1

ricrenzulli@hotmail.com

Email address 2

ricrenzulli@hotmail.com

Are you happy to receive information alongside this report detailing our service & care packages?

No

INSTALLATION DETAILS

All of the below must be completed for us to carry out the commissioning.

Please give details of any special instructions in the box provided at the bottom.

Should we be unable to carry out the work, we reserve the right to make a charge for the full cost of the visit.

Any calls cancelled without 24 hours notice may be charged at the full commissioning cost.

Is adequate purpose built ventilation installed? What percentage has this been calculated 100% at? Is ventilation mechanical or natural? Natural Does the flue comply with BS:6644, Yes BS:5440, IGE UP/10 & CE Approved? How is the flue installed? Horizontally Has the electrical supply been connected Yes with option to isolate? Has water been connected, boiler filled and air removed? Has the gas been connected and purged? Yes Have external controls been Yes commissioned & operational? Is a permanent light available in the boiler Yes room? Is the boiler showing any faults? No
Is ventilation mechanical or natural? Natural Does the flue comply with BS:6644, Yes BS:5440, IGE UP/10 & CE Approved? How is the flue installed? Horizontally Has the electrical supply been connected Yes with option to isolate? Has water been connected, boiler filled and air removed? Has the gas been connected and purged? Yes Have external controls been Yes commissioned & operational? Is a permanent light available in the boiler Yes room? Is the boiler showing any faults? No
Does the flue comply with BS:6644, BS:5440, IGE UP/10 & CE Approved? How is the flue installed? Horizontally Has the electrical supply been connected Yes with option to isolate? Has water been connected, boiler filled Yes and air removed? Has the gas been connected and purged? Yes Have external controls been Yes commissioned & operational? Is a permanent light available in the boiler Yes room? Is the boiler showing any faults? No Is the boiler showing any faults? No
How is the flue installed? Horizontally Has the electrical supply been connected Yes with option to isolate? Has water been connected, boiler filled Yes and air removed? Has the gas been connected and purged? Yes Have external controls been Yes commissioned & operational? Is a permanent light available in the boiler Yes room? Is the boiler showing any faults? No
Has the electrical supply been connected Yes with option to isolate? Has water been connected, boiler filled Yes and air removed? Has the gas been connected and purged? Yes Have external controls been Yes commissioned & operational? Is a permanent light available in the boiler Yes room? Is the boiler showing any faults? No Is the boiler showing any faults? No
Has water been connected, boiler filled and air removed? Has the gas been connected and purged? Yes Have external controls been Yes commissioned & operational? Is a permanent light available in the boiler Yes room? Is the boiler showing any faults? No Is the boiler showing any faults? No
Has the gas been connected and purged? Yes Have external controls been Yes commissioned & operational? Is a permanent light available in the boiler Yes room? Is the boiler showing any faults? No Is the boiler showing any faults? No
Have external controls been commissioned & operational? Is a permanent light available in the boiler Yes room? Is the boiler showing any faults? No Is the boiler showing any faults? No
commissioned & operational? Is a permanent light available in the boiler Yes room? Is the boiler showing any faults? No Is the boiler showing any faults? No
Is the boiler showing any faults? No Is the boiler showing any faults? No
Is the boiler showing any faults?
Is the boiler fully accessible? Yes
Is adequate onsite parking available? Yes
Has the system been cleansed before Yes installation?
Has the system been dosed since Yes installation?

COST BREAKDOWN		
Commissioning costs		
Heat 2	£0.00	
Total Commissioning Costs	£0.00	
Site induction costs		
20 minute induction	£0.00	
Additional	£0.00	
Total Induction Costs	£0.00	
Total Costs	20.02	

CONFIRMATION BY

Full name	Email address
Richard Renzulli	ricrenzulli@hotmail.com

I confirm that I have completed this form as accurately as possible and that any incorrect information provided may lead to delays and/or return visits, which may be chargeable. I am aware that my requested commissioning date may not be available.

Confirmation of your visit date will be supplied within 2 working days

I confirm I have read the Terms & Conditions of use for keston.co.uk. As a data controller, Keston Boilers Ltd take the protection of your personal data seriously. To view our Privacy Policy, please click here.